SERVICE PROCEDURE

14521 JANUARY 2015

SUBJECT: EMISSIONS RECALL

Navistar has decided that a defect which relates to engine emissions exists in certain Continental Mixer, LoneStar®, PayStar®, ProStar®, TranStar®, and WorkStar model trucks built 22 January 2013 thru 3 May 2013 with 2013 model year MaxxForce®

13 engines.

DEFECT DESCRIPTION

This emissions recall applies to truck models that were built with 2013 model year MaxxForce® 13 (EGR) engines and will require recalibration of the engine ECM. This will re-enable On Board Diagnostic monitor and fault reaction.

MODELS INVOLVED

This emissions recall involves certain Continental Mixer, LoneStar®, PayStar®, ProStar®, TranStar®, and WorkStar model trucks built 22 January 2013 thru 3 May 2013 with 2013 model year MaxxForce® 13 engines.

ELIGIBILITY

This procedure applies ONLY to vehicles marked in the Navistar Service PortalSM with emissions recall 14521. Also complete any other open campaigns listed on the Service Portal at this time.

PARTS INFORMATION

There are no parts for this emissions recall.

SERVICE PROCEDURE

WARNING! TO PREVENT PROPERTY DAMAGE, PERSONAL INJURY, AND / OR DEATH, PARK VEHICLE ON HARD FLAT SURFACE, TURN THE ENGINE OFF, SET THE PARKING BRAKE AND INSTALL WHEEL CHOCKS TO PREVENT THE VEHICLE FROM MOVING IN BOTH DIRECTIONS.

WARNING! TO PREVENT PERSONAL INJURY AND / OR DEATH, ALWAYS WEAR SAFE EYE PROTECTION WHEN PERFORMING VEHICLE MAINTENANCE.

WARNING! TO PREVENT PROPERTY DAMAGE, PERSONAL INJURY, AND /OR DEATH, ALLOW COMPONENTS IN ENGINE COMPARTMENT TO COOL BEFORE SERVICING ENGINE OR VEHICLE.

WARNING! TO PREVENT PROPERTY DAMAGE, PERSONAL INJURY, AND / OR DEATH, KEEP FLAMES OR SPARKS AWAY FROM VEHICLE AND DO NOT SMOKE WHILE SERVICING THE VEHICLE'S BATTERIES. BATTERIES EXPEL EXPLOSIVE GASES.

- 1. Park the vehicle on a flat surface with the wheels straight ahead.
- 2. Shift the transmission to park or neutral and set the parking brakes.
- 3. Install wheel chocks.
- 4. Verify that ECM has latest software by referring to vehicle calibration scorecard in Service Portal system.
 - a. If calibration scorecard indicates that calibration is not current, engine must be reprogrammed to raise calibration to latest level. Proceed to Step 5.
 - b. If calibration scorecard indicates calibration is current, engine does not need to be reprogrammed.
 - i. No further action is required for dealers and customers operating outside California. Proceed to Step 7.
 - ii. Dealers and customers operating in California must also perform Step 8.

NOTE: If AutoUpgrade functionality is not available, use NETS.

NOTE: If vehicle you are working on has custom programmable parameters, and you are using NETS, and programming as a blank module, Save a ServiceMaxx™ template of all parameters before programming so the custom programmable parameters can be reset after programing.

5. Program ECM using NETS or AutoUpgrade.

For instructions, refer to IK2600010 – NETS Programming and Troubleshooting Guide. Use Update to Latest Calibration programming option, or IK2600082 – Auto Upgrade Programming Instructions.

These articles contain general information about each reprogramming method and software, with links to specific instructions.

- 6. If assistance is needed, contact Vehicle Programming by creating an iKNow case file or calling 1-800-336-4500, options 3, 1, 1.
- 7. Remove wheel chocks.

Additional Requirements for Dealers and Customers Operating in California

NOTE: The following step is required only for dealers and customers operating in the state of California.

- 8. After completing this recall, dealer must fill out salmon-colored Proof of Correction certificate and provide a copy to customer.
 - Use either Figure 1 (certificate to color print on white paper) or Figure 2 (certificate to print on salmon-colored paper) to print DMV certificates.

	Vehicle Emission Recall - Proof of Correction										
Lic	ense Number	Make	Year Model	Body Type	Vehicle Identification Number						
	Manufacturer Recall Number The above described vehicle has been repaired, modified and/or equipped with new emission control devices to meet applicable California Emission Control Laws. Dealer's Address, City, State										
	Dealership's Authorized X Return this certificate to DMV only when required - otherwise retain for your records.										

0000047743

Figure 1. DMV Certificate, Salmon (Print on 8.5 x 11 inch White Paper).

	Vehicle Emission Recall - Proof of Correction									
Lice	ense Number	Make	Year Model	Body Type	Vehicle Identification Number					
	Manufacturer Recall Number The above described vehicle has been repaired, modified and/or equipped with new emission control devices to meet applicable California Emission Control Laws.									
	Deale		Address, C	tity, State						
	Dealership's Authorized									
	Return this certificate to DMV only when required - otherwise retain for your records.									

0000047729

Figure 2. DMV Certificate, White (Print on 8.5 x 11 inch Salmon Paper).

END OF SERVICE PROCEDURE

LABOR INFORMATION

Operation Number	Description	Time
A40-14521-1	Recalibrate ECM	0.5

CAMPAIGN IDENTIFICATION LABEL

Each vehicle corrected in accordance with this campaign must be marked with a CTS-1075 Campaign Identification Label.

Complete the label and attach on a clean surface next to the vehicle identification number (VIN) plate.




ADMINSTRATIVE/DEALER RESPONSIBILITIES

WARRANTY CLAIMS

Warranty claim expense is to be charged to Warranty. Claims are to be submitted in the normal manner, making reference to Emissions Recall 14521.

It is important that the coding be completed properly to assist in processing the warranty claim. Complete instructions will be found in the Warranty Policy Manual, Section 7.1.8.

As with all claim submission, items acquired locally must be submitted in the "Other Charges" tab. The cost of any bulk items (such as a bag of cable tie straps, roll of wire, barrel of oil, tube of silicone) should be prorated for the cost of the individual pieces/amount used during each repair.



UNITED STATES AND POSSESSIONS

Dealers must correct all vehicles subject to this campaign at no charge to the owner, regardless of mileage, age of vehicle, or ownership, from this time forward.

Dealers should proceed immediately to make necessary correction to units in inventory. All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer or delivery. If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified immediately from your dealer location.

Dealers must make every effort to promptly schedule an appointment with each owner to repair his or her vehicle as soon as possible. However, consistent with the customer notification, dealers are expected to complete the repairs on the mutually agreed upon service date.

Dealers involved in the recall process will be furnished a listing of owner names and addresses to enable them to follow up with owners and have the vehicles corrected. Use of this listing must be limited to this campaign because the list may contain information obtained from state motor vehicle registration records and the use of such motor vehicle registration data for purposes other than this campaign is a violation of law in several states.

CANADA

Dealers must correct all vehicles subject to this campaign at no charge to the owner, regardless of mileage, age of vehicle, or ownership, from this time forward.

Dealers should proceed immediately to make necessary correction to units in inventory. All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer or delivery. If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified immediately from your dealer location.

Dealers must make every effort to promptly schedule an appointment with each owner to repair his or her vehicle as soon as possible. However, consistent with the customer notification, dealers are expected to complete the repairs on the mutually agreed upon service date.

Dealers involved in the recall process will be furnished a listing of owner names and addresses to enable them to follow up with owners and have the vehicles corrected. Use of this listing must be limited to this campaign because the list may contain information obtained from state motor vehicle registration records and the use of such motor vehicle registration data for purposes other than this campaign is a violation of law in several states.

EXPORT

Export Distributors should proceed immediately to make necessary correction to units in inventory. All inventory vehicles subject to this recall campaign must be corrected prior to sale, transfer or delivery. If vehicles have been sold or transferred and you are in receipt of Customer Notification Letters and Authorization for Recall Service cards for those vehicles, the transfer location or customer must be notified immediately from your distributor location.

Export Distributors are to submit warranty claims in the usual manner making reference to this recall number.

Export Distributors are expected to provide full cooperation and follow-up with respect to this important subject matter. If you have any questions or need further assistance, please contact the Regional Service Manager at your regional office.

NAVISTAR, INC